




Outer Frames



Vents



Transoms / Mullions & Beads



SECTION IDENTIFICATION CHART - NOT TO SCALE - NOVEMBER 2008 - 1

For more information please contact the Beaufort Technical Department on: 01633 29 40 40

Tel: 01633 29 40 40 Fax: 01633 29 40 41

www.beaufortsecure.com

